

NOTES:

fall zones-to cushion a fall, shock absorbing material should extend a minimum of 6' in all directions from stationary pieces of play equipment.

routine maintenance-periodically inspect the play equipment to check on missing, broken, or worn out components; securing hardware; checking for deterioration in the wood, metal, or plastic materials; and maintaining the proper 12" depth of surfacing material.

